



**C&K**  
C&K Testing

# Test Report

**Report No.: TR20165450**

Applicant

Bagco Asia Ltd

Address

Suite 1902, Tamson Plaza, 161 Wai Yip Street,  
Kwun Tong, Kowloon

Report Date

2016-08-19

**Hangzhou C&K Testing Technic Co., Ltd.**

---

Hangzhou C&K Testing Technic Co., Ltd

Add : 1/F, No. 4 Building, Huaye Hi-Tech Industrial Park, No. 1180, Bin'an Road, Binjiang District, Hangzhou 310052, China.

Hotline : 4006-721-723    Lab Tel : +86 571-8720 6535    Fax : +86 571-8990 0719    E-mail : test@cirsgroup.com    Website : www.cirs-ck.com

The result(s) shown in this report refer only to the sample(s) tested unless otherwise stated. This report shall not be reproduced except in full, without written prior approval of Hangzhou C&K Testing Technic Co., Ltd.



## Test Report

<b>Applicant</b>	Bagco Asia Ltd
<b>Address</b>	Suite 1902, Tamson Plaza, 161 Wai Yip Street, Kwun Tong, Kowloon
<b>Sample Name</b>	Koskin PVC
<b>Type/ Model</b>	/
<b>Sample Received Date</b>	2016-08-15
<b>Test Period</b>	2016-08-15~ 2016-08-19
<b>Test Requirement</b>	To determine the following items in the submitted sample(s) according to the client's requirement.

<b>Test Item(s)</b>	<b>Test Result(s)</b>
Cadmium Content	Pass

Complied by

*Crystal Su*

Inspected by

*Kale Zhang*

Authorized by


*Mark Li*



**Test Component(s):**

No.	Sample Serial No.	Test Component(s)
001	TR20165450001	Koskin PVC

**Photo(s):**



TR20165450



### Cadmium Content

Test Method: EN 1122-2001

Test Item(s)	MDL	Clients' Requirement	Unit	Test Result(s)
				001
Cadmium	5	90	mg/kg	N.D.

Remarks:

1. MDL = Method Detection Limit
2. N.D. = Not detected (<MDL)

\*\*\*The end of report\*\*\*