



C&K
C&K Testing

Test Report

Report No.: TR20165142

Applicant

Bagco Asia Ltd

Address

Suite 1902, Tamson Plaza, 161 Wai Yip Street,
Kwun Tong, Kowloon

Report Date

2016-08-10

Hangzhou C&K Testing Technic Co., Ltd.

Hangzhou C&K Testing Technic Co., Ltd

Add : 1/F, No. 4 Building, Huaye Hi-Tech Industrial Park, No. 1180, Bin'an Road, Binjiang District, Hangzhou 310052, China.

Hotline : 4006-721-723 Lab Tel : +86 571-8720 6535 Fax : +86 571-8990 0719 E-mail : test@cirsgroup.com Website : www.cirsgroup.com

The result(s) shown in this report refer only to the sample(s) tested unless otherwise stated. This report shall not be reproduced except in full, without written prior approval of Hangzhou C&K Testing Technic Co., Ltd.



Test Report

| | |
|-----------------------------|---|
| Applicant | Bagco Asia Ltd |
| Address | Suite 1902, Tamson Plaza, 161 Wai Yip Street, Kwun Tong, Kowloon |
| Sample Name | 210D polyester w/ PU backing-New Navy |
| Type/ Model | / |
| Sample Received Date | 2016-08-03 |
| Test Period | 2016-08-03~ 2016-08-10 |
| Test Requirement | To determine cadmium content in the submitted sample according to the client's requirement. |

| | |
|---------------------|-----------------------|
| Test Item(s) | Test Result(s) |
| Cadmium Content | Pass |

Complied by

Crystal Su

Inspected by

Kale Zhang

Authorized by


Mark Li



Test Component(s):

| No. | Sample Serial No. | Test Component(s) |
|-----|-------------------|---------------------------------------|
| 001 | TR20165142001 | 210D polyester w/ PU backing-New Navy |

Photo(s):



TR20165142



Cadmium Content

Test Method: EN 1122-2001

| Test Item(s) | MDL | Clients' Requirement | Unit | Test Result(s) |
|--------------|-----|-------------------------|-------|----------------|
| | | | | 001 |
| Cadmium | 5 | 90 | mg/kg | N.D. |

Remarks:

1. MDL = Method Detection Limit
2. N.D. = Not detected (<MDL)

The end of report