



# Test Report

**Report No.: TR20165224**

Applicant	Bagco Asia Ltd
Address	Suite 1902, Tamson Plaza, 161 Wai Yip Street, Kwun Tong, Kowloon
Report Date	2016-08-11

**Hangzhou C&K Testing Technic Co., Ltd.**

Hangzhou C&K Testing Technic Co., Ltd

Add : 1/F, No. 4 Building, Huaye Hi-Tech Industrial Park, No. 1180, Bin'an Road, Binjiang District, Hangzhou 310052, China.

Hotline : 4006-721-723    Lab Tel : +86 571-8720 6535    Fax : +86 571-8990 0719    E-mail : test@cirsgroup.com    Website : www.cirsgroup.com

The result(s) shown in this report refer only to the sample(s) tested unless otherwise stated. This report shall not be reproduced except in full, without written prior approval of Hangzhou C&K Testing Technic Co., Ltd.



## Test Report

<b>Applicant</b>	Bagco Asia Ltd
<b>Address</b>	Suite 1902, Tamson Plaza, 161 Wai Yip Street, Kwun Tong, Kowloon
<b>Sample Name</b>	Jute fabric w/ LDPE Lamination-Black
<b>Type/ Model</b>	/
<b>Sample Received Date</b>	2016-08-05
<b>Test Period</b>	2016-08-05~ 2016-08-11
<b>Test Requirement</b>	To determine Organic Tin Content in the submitted sample(s) according to article 20, Annex XVII of REACH Regulation (EC) No 1907/ 2006.

<b>Test Item(s)</b>	<b>Test Result(s)</b>
Organic Tin Content	Pass

Complied by

*Crystal Su*

Inspected by

*Kale Zhang*

Authorized by


*Mark Li*



**Test Component(s):**

No.	Sample Serial No.	Test Component(s)
001	TR20165224001	Jute fabric w/ LDPE Lamination-Black

**Photo(s):**



TR20165224





### Organic Tin Content

Test Method: EPA 3550C: 2007, EPA 8270D: 2007

Test Item(s)	MDL	Limit	Unit	Test Result(s)
				001
Dibutyltin chloride (DBT)	100	1000	mg/kg	N.D.
Tributyltin chloride (TBT)	100	1000	mg/kg	N.D.
Dioclyldichlorotin (DOT)	100	1000	mg/kg	N.D.
Triphenyltin Chloride (TPT)	100	1000	mg/kg	N.D.

Remarks:

1. N.D. = Not detected (<MDL).
2. MDL= Method Detection Limits;

\*\*\*The end of report\*\*\*